



**Wiring Diagram - SM-6695H**

Enclosure Locations  
 E1 Left E2 Back

Item	Part #	Description	Item	Part #	Description	Item	Part #	Description
M1	3.3.01.07.010	Motor—450W	S4	3.1.03.04.011	Draw Sensor	JR	3.1.01.02.012	Thermal Relay
M2	3.2.01.02.038	Compressor	S5	3.1.03.04.009	Low Milk Sensor	PC	2.1.1.30.0010	Control Board
M3	3.2.03.04.003	Fan Motor	KM	3.1.01.01.011	Contactor	TH1	3.1.01.07.002	Thermostat - C
S1	3.2.04.06.004	Pressure Switch	D	3.2.04.04.016	Solenoid Coil	TH2	3.1.01.07.003	Thermostat - H
S3	3.1.03.03.002	Power Switch	T	3.1.01.04.006	Transformer			