


E2 Enclosure



Wiring Diagram - SM-6490H

| Item | Part # | Description | Item | Part # | Description | Item | Part # | Description | Item | Part # | Description |
|------|---------------|-------------------|------|---------------|-----------------|-------|---------------|----------------|------|---------------|---------------|
| M1 | 3.3.01.07.001 | Motor - 250W | KM | 3.1.01.01.011 | Contactors | S5 | 3.1.03.04.009 | Low Mix Sensor | BELL | 3.1.02.15.003 | Low Mix Alarm |
| M2 | 3.2.01.02.028 | Compressor - Main | JR | 3.1.01.02.012 | Thermal Relay | S8 | 3.1.03.02.002 | Torque Switch | PCB | 2.1.1.30.0012 | Control Board |
| M3 | 3.2.03.04.003 | Fan Motor - Main | T | 3.1.01.04.006 | Transformer | S9/10 | 3.1.01.07.003 | Thermostat | S3 | 3.1.03.03.002 | Power Switch |
| M6 | 3.3.01.01.003 | HA Motor | S1 | 3.2.04.06.004 | Pressure Switch | S11 | 3.1.03.04.015 | Standby Switch | | | |
| D | 3.2.04.04.016 | Solenoid Coil | S4 | 3.1.03.01.004 | Draw Switch | LAMP | 3.1.02.14.001 | Low Mix Light | | | |