



**SCHEMA DE CABLAGE PONY4 380-400-415V tri  
WIRING DIAGRAMS PONY 4 380-400-415V three-phase**








**SCHEMA DE CABLAGE PONY 2 230V MONO**  
**WIRING DIAGRAM PONY 2 230V single-phase**




CABLE D'ALIMENTATION GÉNÉRIQUE  
 MAIN POWER CABLE

**SCHEMA DE CABLAGE PONY 2 110V MONO**  
**WIRING DIAGRAM PONY 2 110V single-phase**




# 2 DOUBLE GROUPE

380 / 400 / 415V TRI + N +  $\perp$



110 / 200 / 230 / 240 V MONO +  $\perp$



# 1 DOUBLE GROUPE

110 / 200 / 230 / 240 V MONO +  $\perp$

