

MOTOR BLOCK PMDH / PMF 250

Parts list	Code	List \$ Price
Motor brushes (2)	0514	19.61
Ball bearing	0601	19.61
Squeezing washer	0726	2.75
Wall bracket	0880	99.52
Non-locking switch	0908	41.06
Capacitor	0909	17.39
Strain relief 230 V	0950	3.44
Strain relief 115V	0950.1	3.44
Warning label	1017	6.90
Dynamic label	1027	17.11
Label w/ serial number 230 V	1071	7.17
Label w/ serial number 115 V	1072	7.17
Variable speed control board 230 V	1213	135.95
Variable speed control board 115 V	1214	118.15
Spacer screws (4)	7903	6.37
Spacer rods (4)	7913.F	22.12
Variable speed control knob	8609	19.12
Power cord 230 V	9011	30.44
Stator screws (2)	9023	5.18
Self-lubricating ring	9025	5.98
Coupler for armature	9028	13.08
Power cord 115 V	9040	38.09
Handle screws (3)	9502	0.84
Switch protector	9813	11.87
Upper motor casing	9817	61.17
Fan	9818	14.12
Rotor w/o coupling 230 V	9819	331.07
Rotor w/o coupling 115 V	9819.1	331.07
Stator 230 V w/carter. carbon brushes holders	9820	331.07
Stator 115 V w/carter. carbon brushes holders	9820.1	331.07
Upper half handle	9832	35.89
Complete handle 230 V	9840	173.64
Complete handle 115 V	9840.1	173.64
Lower half handle w/ label 230 V	9841	39.97
Lower half handle w/ label 115 V	9841.1	39.97
Aluminium carter	9842	184.07
BM 250 Motor block (see machine catalog)	AC005	-

