



JUMPERS CAN NOT BE REMOVED FROM PC BOARD. J31 THRU J34 FORM A SERIES CIRCUIT, IF A JUMPER IS REMOVED AND DISCARDED THE PC BOARD TIMING FUNCTIONS WILL NOT WORK PROPERLY.



