



WIRING DIAGRAM
MODEL 30FS2

SEE SERIAL PLATE FOR CORRECT POWER SOURCE
115 VAC, 60 Hz, 1 PHASE
OR
220 VAC, 60/50 Hz, 1 PHASE

