



# WIRING DIAGRAM



# WIRING DIAGRAM




WIRING DIAGRAM, ELECTRIC KETTLES  
24, 36 & 43.2 K.W. - 208/240 VOLT 3 PHASE


HEATING ELEMENTS  
24 K.W. - 12 K.W. EA.  
36 K.W. - 18 K.W. EA.  
43.2 K.W. - 21.6 K.W. EA.

CONTACTORS-40 AMP FOR 24 K.W. @ 208/240 VOLT  
CONTACTORS-50 AMP FOR 36 K.W. @ 240 VOLT  
CONTACTORS-60 AMP FOR 36 K.W. @ 208 VOLT, 43.2 K.W. @ 208/240 VOLT

# WIRING DIAGRAM



# WIRING DIAGRAM



3 PHASE WIRING DIAGRAM  
FOR ELECTRIC KETTLES  
208, 220 & 240 VOLTS

CONTACTOR-40 AMP FOR 12 K.W. @ 208/240 VOLT  
 CONTACTOR-50 AMP FOR 18 K.W. @ 240 VOLT  
 CONTACTOR-60 AMP FOR 18 K.W. @ 208 VOLT