







SG4 and SG6 Models
SOLID STATE CONTROL WIRING DIAGRAM

CONNECT 200-240 VOLT SUPPLY TO L1 & L2

120 VOLT UNITS PROVIDED WITH 3 PRONG GROUNDED PLUG.